


NATURE OF SAMPLES FOR HRSEM



NOTE:

- Samples should be completely dried.
- Oil/Wax/Resins/Liquid crystals/Degassing/Emulsion/Moisture absorbing samples cannot be analyzed here.
- Magnetic samples can be allowed only in the form of bulk/pellet.
- All liquid samples should be dried over a glass slide/ cover slip.
- Sputter Coating (Au) will be done only for non-conducting samples.